## Figure E-10 Statutory Checklist

## STATUTORY CHECKLIST [§58.35(a) activities]

## for Categorical Exclusions and Environmental Assessments

Note: Review of the items on this checklist is required for both Categorical Exclusions under Sec. 58.35(a) and projects requiring an Environmental Assessment under Sec. 58.36. If no compliance with any of the items is required, a Categorical Exclusion [58.35(a)] may become "exempt" under the provisions of Sec. 58.34 (a) (12). In such cases attach the completed Statutory Checklist to a written determination of the exemption. Projects requiring an Environmental Assessment under Sec. 58.36 cannot be determined to be exempt even if no compliance with Statutory Checklist items is found. Three items listed at Sec. 58.6 are applicable to all projects, including those determined to be exempt.

## Project Name and Identification No. CDBG-DR Project 2149 – 896-898 Howard Avenue, Bridgeport

Area of Statutory or Regulatory Compliance	Not Applicable to This Project	Consultation Required*	Review Required*	Permits Required*	Determination of consistency Approvals, Permits Obtained*	Conditions and/or Mitigation Actions Required	Provide compliance documentation. Additional material may be attached.				
Document Laws and authorities listed at 24 CFR Sec. 58.5											
Historic Properties     [58.5(a)] [Section 106 of NHPA]							See attachment 1 for determination statement from CT State Historic Preservation Office. Project activities will have no adverse effects on the state of Connecticut's historic resources.				
2. Floodplain Management [58.5(b)] [Ex Or 11988] [24 CFR 55]							National Flood Insurance Program (NFIP), Flood Insurance Rate Map (FIRM) Number 09001C0437G, Revised July 8, 2013 Identifies the property at 896-898 Howard Avenue, Bridgeport, CT, outside Zone A and AE for a 100 Year Flood. See attachment 2 for documentation.				
3. Wetland Protection [58.5 (b)]							United States Fish and Wildlife Services (USFWS), National Wetlands Inventory (NWI) mapping identifies the project site outside a wetland zone. See attachment 3 for map documentation. Mapping is Geographic Information System (G.I.S.) map created using data accessed from USFWS NWI website at http://www.fws.gov/wetlands/Data/State-Downloads.html				
4. Coastal Zone Management [58.5(c)]							Site at 896-898 Howard Avenue, Bridgeport, CT is shown located outside the Coastal Boundary Area. See attachment 4 for map documentation. Mapping is Geographic Information System (G.I.S.) map created using data accessed from CT Environmental Conditions Online (CT ECO) of the Coastal Boundary Zone from http://www.cteco.uconn.edu/				
5. Water Quality – Aquifers [58.5(d)] [40 CFR 149]							On site water and sewer facilities are not included in rehabilitation work for 896-898 Howard Avenue, Bridgeport, CT. Connecticut DEEP Bureau of Water Protection and Land Reuse map titled 'Connecticut Aquifer Protection Areas' dated December 16, 2013 does not identify aquifer protection areas in				

Area of Statutory or Regulatory Compliance	Not Applicable to This Project	Consultation Required*	Review Required*	Permits Required*	Determination of consistency Approvals, Permits Obtained*	Conditions and/or Mitigation Actions Required	Provide compliance documentation. Additional material may be attached.  the City of Bridgeport Connecticut near the project site. See
6. Endangered Species [58.5(e)] [16 U.S.C. 1531 et seq.]							attachment 5 for documentation.  Project is located outside mapped Natural Diversity Data Base (NDDB) areas from CT DEEP. See attachment 6A for Geographic Information System (G.I.S.) map of NDDB areas created using data accessed from Connecticut Environmental Conditions Online (CT ECO) at http://www.cteco.uconn.edu/. U.S. Fish & Wildlife Servce Information, Planning, and Conservation (IPaC) List, included as attachment 6B, does not identify any Endangered Species, Critical Habitats, or Wildlife
7. Wild and Scenic Rivers [58.5 (f)] [16 U.S.C. 1271 et seq.]							Refugees in the project site.  Project site is not proximate to the Eight Mile River or the Farmington River West Branch listed in the National Wild and Scenic Rivers System.
8. Air Quality [58.5(g)] [42 U.S.C. 7401 et seq.]							No quantifiable increase in air pollution is measurable for proposed rehabilitation activities.
9. Farmland Protection [58.5(h)]							All activity will occur inside existing structure foot print and no change in land use is proposed.
Manmade Hazards 10 A. Thermal Explosive [58.5(i)]							Per 24 CFR 51 Subpart C and HUD Guidebook 6600.G rehabilitation work that does not alter the number dwelling units or a change of land use is not subject to Acceptable Separation Distance (ASD) requirements for HUD assisted projects near hazardous operations handling petroleum products or chemicals of an explosive or flammable nature.
10 B. Noise [58.5(i)]							Noise Abatement and Control requirements per 24 CFR 51.101(a)(3) are not applicable to HUD assisted projects which restore facilities substantially as they existed prior to a disaster.
10 C. Airport Clear Zones [58.5 (i)]							The residential structure at 896-898 Howard Avenue, Bridgeport, CT is located outside the Runway Clear Zone of Tweed/New Haven Commercial Airport.
10 D. Toxic Sites [58.5 (i)(2)(i)]							The project site at 896-898 Howard Avenue, Bridgeport, CT is,  1. Not listed on EPA's NPL Lists (Proposed and Final) or the State of Connecticut's Superfund Priority List;  2. Not listed in Comprehensive Environmental Response and Compensation Liability Information System (CERCLIS) database search as a Comprehensive Environmental Response and Compensation Liability Act (CERCLA) site;  3. Not located within 3,000 feet of a landfill site as listed on CT DEEP's active landfill list;  4. Not listed on CT DEEP's Underground Storage Tank list

Area of Statutory or Regulatory Compliance	Not Applicable to This Project	Consultation Required*	Review Required*	Permits Required*	Determination of consistency Approvals, Permits Obtained*	Conditions and/or Mitigation Actions Required	Provide compliance documentation. Additional material may be attached.		
							Not listed on CT DEEP's list of potentionally contaminated sites and is not known or suspected to be contaminated by toxic chemicals or radioactive materials		
11. Environmental Justice [58.5(j)]							The rehabilitation work at the project site, 896-898 Howard Avenue, Bridgeport, CT, is compatible with the surrounding residential use and no adverse human health and environmental effects on minority or low income populations are expected. The City of Bridgeport, Connecticut is listed by the Connecticut Department of Economic and Community Development (CT DECD) as a distressed municipality as defined in C.G.S. Section 22a-20. See attachment 7 for the 2013 listing of distressed municipalities in CT from the CT DECD in which City of Bridgeport, CT is listed.		
Document Laws and authorities listed at Sec. 58.6 and other potential environment									
12 A. Flood Insurance [58.6(a) & (b)]							National Flood Insurance Program (NFIP), Flood Insurance Rate Map (FIRM) Number 09001C0437G, Revised July 8, 2013 identifies the property at 896-898 Howard Avenue,Bridgeport, CT, outside Zone A and AE for a 100 Year Flood. See attachment 2 for documentation.		
12 B. Coastal Barriers [58.6(c)]							Project at 896-898 Howard Avenue, Bridgeport, CT is not located within a Coastal Barrier Resource System unit. See attachment 8 for documentation. Mapping is Geographic Information System (G.I.S.) map created using data digitized from official John H. Chafee Coastal Barrier Resource System maps enacted by law and endorsed by the U.S. Fish and Wildlife Service. Digital data was accessed from CT Environmental Conditions Online (CT ECO) at http://www.cteco.uconn.edu/		
12 C. Airport Clear Zone Notification [58.6(d)]	$\boxtimes$						Project does not involve the puchase or sale of a property as such 24 CFR 58.6(d) is not applicable.		
13 A. Solid Waste Disposal [42 U.S.C. S3251 et seq.] and [42 U.S.C. 6901-6987 eq seq.]	$\boxtimes$						Rehabilitation activities to the residential structure at the project site, 896-898 Howard Avenue, Bridgeport, CT, are not expected to affect the capacties of solid waste disposal services.		
13 B. Fish and Wildlife [U.S.C. 661-666c]	$\boxtimes$						Project activites will not result in impounding, diverting, deepening, channelizing or modification of any stream or body of water. Project is not a water control project.		
13 C. Lead-Based Paint [24 CFR Part 35] and [40 CFR 745.80 Subpart E]							Residential Structure at 896-898 Howard Avenue was built prior to 1978. The results of a Lead Paint Survey are included in attachment 9, 'Hazardous Materials Inspection Report, '896-898 Howard Avenue, Bridgeport CT', dated 13 October 2014, prepared by Facility Support Services, LLC. Lead based paint		

Area of Statutory or Regulatory Compliance	ect				*pe	Ē	Provide compliance documentation. Additional material may be attached.
	Not Applicable to This Project	Consultation Required*	Review Required*	Permits Required*	Determination of consistency Approvals, Permits Obtained*	Conditions and/or Mitigation Actions Required	
			-				hazards identified in the survey will be abated or addressed with interim controls where appropriate per attachment 10, 'Abatement Plan for 896-898 Howard Avenue, Bridgeport, Ct' prepared by Gilbertco Lead Inspections LLC.
13 D. Asbestos							No Asbestos Containing Materials (ACM's) were identified in sampled materials to be disturbed by project work. Results of sampled materials testing are included in attachment 9, 'Hazardous Material Inspection Report, 896-898 Howard Avenue, Bridgeport, CT", 13 October 2014, prepared by Facility Support Services, LLC.
13 E. Radon [50.3 (i) 1]							Radon levels requiring mitigation were not found at the project site. Results of testing are included in attachment 9, 'Hazardous Material Inspection Report, 896-898 Howard Avenue, Bridgeport, CT', 13 October 2014, prepared by Facility Support Services LLC.
13 F. Mold							No specific regulation regarding the levels requiring mold mitigation or abatement are enacted by law in the State of Connecticut. Accelerated mold growth is indicated by testing results at the project site. The procedures and results of the microbial testing for mold spores conducted at the project site are included in attachment 9, 'Hazardous Material Inspection Report 896-898 Howard Avenue Bridgeport, CT', 13 October 2014, prepared by Facility Support Services, LLC. Mold Abatement following guidelines mandated in Public Act No. 06-195, as described in document entitled 'Connecticut Guidelines for Mold Abatement Contractors' published by the Connecticut Department of Public Health, Environmemntal & Occupational Health Assessment Program will be required. See attachment 11 for 'Microbial (Mold) Abatement Work Plan.'
Other: State or Local 14 A. Flood Management Certification [CGS 25-68]							National Flood Insurance Program (NFIP), Flood Insurance Rate Map (FIRM) Number 09001C0437G, Revised July 8, 2013Identifies the property 896-898 Howard Avenue,Bridgeport, CT, outside Zone A and AE for a 100 Year Flood. See attachment 2 for documentation.
14 B. Structures, Dredging & Fill Act [CGS 22a-359 to 22a-363f]							Rehabilitation work at project site does not propose any adverse impacts to coastal resources nor propose any activity waterward of the coastal jurisdiction line.
14 C. Tidal Wetlands Act [CGS 22a-28 to 22a-35]							Connecticut Department of Energy and Environmental Protection Tidal Wetlands Mapping as defined in C.G.S. Section 22a-29 and Section 22a-93(7)(e) identifies the project as outside a Tidal Wetland Zone. See attachment 12 for documentation. Mapping is Geographic Information System (G.I.S.) map created using data accessed from CT Environmental Conditions Online (CT ECO) of Tidal Wetlands Mapping accessed from http://www.cteco.uconn.edu/

Area of Statutory or Regulatory Compliance	Not Applicable to This Project	Consultation Required*	Review Required*	Permits Required*	Determination of consistency Approvals, Permits Obtained*	Conditions and/or Mitigation Actions Required	Provide compliance documentation. Additional material may be attached.				
14 D. Local inland wetlands/watercourses [CGS 22a-42]	$\boxtimes$						Project rehabilitation work is not expected to impact wetlands/watercourses.				
14 E. Various municipal zoning approvals		$\boxtimes$		$\boxtimes$			Rehabilitation activites at the project site will need review by City of Bridgeport Building Department for issuance of required building permit.				
DETERMINATION:  This project converts to Exempt, per \$58.349a)(12), because it does not require any mitigation for compliance with any listed statutes or authorities, nor requires any formal permit or license. Funds may be drawn down for this (now) EXEMPT project; OR  This project cannot convert to Exempt because one or more statutes/authories requires consultation or itigation. Complete consultation/mitigation											
requirements, publish NOt/RROF and obtain Authority to Use Grant Funds (HUD 7015.16) per -58.70 and 58.71 before drawing down funds; OR  The unusual circumstances of this project may reasult in a significant environmental impact. This project requires preparation of an Environmental Assessment (EA). Prepare the EA according to 24 CFR Part 58 Subpart E.											
Prepared by:  Tid Couch, P.E., Member Martinez Couch & Associates, LLC.											
Responsible Entity or designee Signature:  Hermia Delaire, CDBG-DR Program Manager  Date											